WARNING about 6C33C tubes

TO AVOID AMPLIFIER
MALFUNCTION,
ALWAYS INSERT THE TUBES INTO
THEIR APPROPRIATE POSITIONS:
TUBE MARKED "V1" ON THE BOX
MUST BE INSERTED INTO THE
CORRESPONDING "V1" POSITION
ON THE AMPLIFIER'S CHASSIS;
THE SAME APPLIES TO "V2" TUBE.

NEVER SWAP THE TUBES.